



## **Construction Safety**

# SSC Construction Inspection Safety Findings/Stats

# November 2011





## **Contact Info:**





Mike Rewis

mike.j.rewis@nasa.gov

228-688-2663 phone

288-688-3701 fax

John Rhodes
john.d.rhodes-1@nasa.gov
228-688-2462 phone
228-688-3701 fax

Daryl Kosturock

daryl.kosturock-1@nasa.gov

228-688-3641 phone

228-688-3701 fax

John Lindsay john.d.lindsay@nasa.gov 228-688-2557 phone 288-688-3503 fax



## **Contact Info:**

A-3 Test Stand



Robert Gargiulo, A-3 Chief Safety Officer robert.f.gargiulo@nasa.gov

228-688-3842 phone

228-688-3701 fax

Jim Deschenes

james.e.deschenes@nasa.gov

228-688-1837 phone

228-688-7619 fax

Donald Smith

donald.g.smith-1@nasa.gov

228-688-1085 phone

228-688-3701 fax

James Gordon
<a href="mailto:james.g.gordon@nasa.gov">james.g.gordon@nasa.gov</a>
228-688-2794 phone
228-688-7619 fax



# Construction Safety Findings: 31 October-04 November 2011



### **Findings Total: 2**

-Serious Findings: 0

-Less than Serious Findings: 0

-Positive findings: 2

- Two workers were observed transitioning between scaffolding and ladders, approximately 200 feet above the ground. Both workers completed their transitions and tasks by properly using their personal fall arrest gear.
- Safety Inspectors noted that all the contractors are conducting well organized safety meetings (Toolbox Talks) at the beginning of each shift to cover items addressed on the SPA's as well as identifying and recording any new tasks or hazards associated with the upcoming shift.

### Mishaps / Close Calls: 1

-Mishap: 0

-Close Call(s): 1

1. A Close Call (#12-008) was submitted on a USACE contractor. The contractor installing a duct bank on the north side of Saturn Drive trenched across the main driveway entrance to B-8000. There were no warning/detour/construction signs placed along the road in the areas leading up to the closed driveway. Once you got to the driveway, you could see it was closed and there was a detour sign hung just in front of the trench. Several motorists had to make illegal and unsafe U-turns.





# Construction Safety Findings: 07-11 November 2011



### Findings Total: 0

-Serious Findings: 0

-Less than Serious Findings: 0

### Mishaps / Close Calls: 0

-Mishap: 0

-Close Call(s): 0

### Other-

1. After reviewing the entire SPA process, it was recommended to adjust the daily SPA to have the living document throughout the shift maintained on site and turned in the following morning as a credibility enhancement initiative, instead of turning in the SPA's at the beginning of the shift.



# Construction Safety Findings: 14-18 November 2011




### **Findings Total: 1**

-Serious Findings: 0

-Less than Serious Findings: 1

1. Scaffolding on Level 10 was found incorrectly erected. Two horizontal members (Ledgers) were found being used as vertical posts (Standards).

### Mishaps / Close Calls: 0





# S MA

# Construction Safety Findings: 21-25 November 2011

### Findings Total: 0

-Serious Findings: 0

-Less than Serious Findings: 0

### Mishaps / Close Calls: 0

-Mishap: 0

-Close Call(s): 0





# SSC Construction Safety: November 2011



OSHA announced the top ten most frequently cited standards following inspections of worksites by federal OSHA during FY 2011. The Scaffolding and Fall Protection standards in Construction were the top two most cited, maintaining their positions from FY 2010. OSHA publicizes this list to alert employers about these frequently cited standards so they can take steps to find and fix recognized hazards addressed in them before a worker suffers a preventable injury, illness or death.

-source: OSHA Quick Takes · November 15, 2011 · Volume 10, Issue 22



## SSC Construction Safety: November 2011



SAFETY NOTICE

110008

November 17: 2011

GS-2669 Modeta

GS-4069

GS6911-101 to GS6912-412 Serial Numbers Affected:

Subject: Machine Instability

Allowable Hours

#### lesue:

Genie has determined that some of the machines in the serial range listed above may have been manufactured incorrectly in the following ways:

- · The hydraulic circuit in the oscillation system may have been assembled incorrectly causing the oscillating axies to function improperly. Improperly functioning oscillating axies can result in loss of machine stability.
- . Aske plyot pins that are out of specifications may have been installed, allowing the axies to be partially supported. Axies that are pertially supported can result in loss of machine.

#### Action Required:

This notice requires the removal of all affected machines from service until the following actions are completed:

- · Rewiring and replumbing of the oscillate system
- . Inspection of the axle pivol pins
- 1. Encate all machines within the model and serial numbers given above.
- 2. Inspect the pole pivot pins and oscillate system using the enclosed instructions.
- 3. Fill out and sign the Completion Form included in the Inspection and Repair instructions and return to Genie. This will verify that this safety notice has been completed on your machine.

Inspection and Repair Instructions

PROCEDURE

REV A




illustration 10

3 At the steer end of the machine locate the axle pivot pin. Refer to illustration 11, item A




illustration 11

- 4 Measure the distance from the chassis bulkhead to the tapered end of the pivot pin towards the center of the machine. Refer to illustration 12
- O It measures 0.250 inches / 6.35 mm or greater. Continue with step 5.
- The pivot pin is less than specified. Tag and remove the machine from service. Contact the Genie parts department for a replacement pin kit. You must reference Safety Notice 110008 when ordering.

Note: If the pivot pin needs to be replaced do not continue to section Test the Oscillate Axle until the pin has been replaced. Do not install the chassis hose cover at this time. It will need to be removed during pin replacement. Lower the platform to the stowed position




illustration 12

Genie



# SSC Construction Safety: November 2011



#### SAFETY ALERT

UNEXPECTED TELESCOPIC FORKLIFT DROPPED LOAD DUE TO CHAIN FAILURE: Highlights need to verify maintenance & inspections













Clearly delineate responsibilities for maintenance and inspections of any heavy equipment (especially when renting) before work begins – NAVFAC QA program representatives will spot check documentation.



# S MA

# SSC Construction Safety: November 2011

Photo shows missing chain on boom spine after a chain failure. Boom section is designed with a chain that travels the length of the boom.








# SSC Construction Safety: November 2011



Several other fractures visible along chain beyond break points. Chain observed with rust and no lubricant.







# SMA SUCCES

# SSC Construction Safety: November 2011

Deficiency: This photo demonstrates an example where some chain lubrication has been applied mostly on the surface, but not enough to penetrate movement contact points.







# S MA

# SSC Construction Safety: November 2011

WHAT TO LOOK FOR: Accurate up to date maintenance records in Activity Hazard Analysis (AHA) before work begins followed by documented visual inspections.







# SSC Construction Safety: November 2011



SHARE # 19 11

http://www.cpsc.gov/





CPSC Home > Current

#### On-line Form for CPSC Subscription Lists

This form allows you to subscribe or unsubscribe to CPSC's email subscription lists (we have prepared a <u>detailed description</u> of our list system to help you make the best subscription choice). Enter your email address, click the list of your choice, and then click "Subscribe" or "Unsubscribe". You can also subscribe and unsubscribe by <u>sending us an email message</u>. If neither method works, please contact webteam@cpsc.gov for assistance.

PLEASE NOTE that our messages are often blocked by anti-spam filters (as they often contain merchandizing



information about product sales) so if you do not receive our messages after joining, set your filter to allow mail from listserv@cpsc.gov or from the domain cpsc.gov - this will usually solve the problem.

If subscribing, a message will be sent to the email address you entered, asking you to confirm your subscription by replying to the message. As per CPSC's <u>privacy policy</u>, we will not disclose your email address or use it for any other purpose. If unsubscribing, a message will be sent to the email address you entered verifying that you unsubscribed.

Check out the <u>USA.gov Subscription</u>	<u>Center</u> for other free federal government newsletters!
	Subscribe Unsubscribe
Only those recalls involving specialty pro	ucts (list name: specialty)
Only those recalls involving household p	oducts (list name: household)
Only those recalls involving products use	outdoors (list name: outdoor)
Only those recalls involving products use	for sports & recreation (list name: recreation)
Only those recalls involving infant/child	roducts (list name: child)
CPSC Public Calendar only (list name: o	lendar)
All recalls only (list name: recalls)	
<ul> <li>All CPSC press releases, including recall</li> </ul>	(list name: releases)
All CPSC press releases and recalls, and	he Public Calendar (list name: all)
ist choice: (if joining, just one list	hould meet most people's requirements; to join a second list, repeat the process)
mail address:	Zip code (optional):

Connect with us!

т2





### **Construction Safety**

Questions?





### **Construction Safety**

## Have a SAFE Holiday Season!