



Construction Safety

SSC Construction Inspection Safety Findings/Stats

May 2019





Contact Info:



NASA Safety

Mike Rewis mike.j.rewis@nasa.gov

228-688-2663 288-688-3701 fax

Elizabeth Calantoni elizabeth.calantoni en asa.gov

228-688-1804 228-688-2760 fax Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-1167

228-688-3701 fax

http://constructionsafety.ssc.nasa.gov/



Contact Info:



BASTION/SACOM Safety

Donald Smith, CHST donald.g.smith-1@nasa.gov 228-688-1085 phone 228-688-3701 fax

John Lindsay, CSP john.d.lindsay@nasa.gov 228-688-2557 phone 288-688-3503 fax Mark Bridenbeck, TES
mark.a.bridenbeck@nasa.gov
228-688-1732 phone
228-688-3701 fax

Will Davis
william.b.davis@nasa.gov
228-688-3193 phone
228-688-3503 fax

http://constructionsafety.ssc.nasa.gov/



S MA

Construction Safety Report: 01 May – 03 May 2019

Findings: 0

Level 1 Severity: 0

(Corrected on the spot)

Level 2 Severity: 0

(Corrective action documented)



Construction Safety Report: 06 May – 10 May 2019



Findings: 2

Level 1 Severity: 1

(Corrected on the spot)

<u>Sanitary Sewer Recapitalization Project (80SSC018F0044):</u> On May 06, 2019 a contractor was observed using a power saw to cut steel creating sparks within 20 feet of an above ground Diesel storage tank. They did not have a Hot Work Permit. Work was stopped until the required permit was issued. Ref: SCWI-8838-0002. Sec 5.0. Item b. SHEtrak Closed # 102701

Level 2 Severity: 1

(Corrective action documented)

<u>Sanitary Sewer Recapitalization Project (80SSC018F0044):</u> On May 06, 2019 a contractor was using a product on SSC without first submitting the SDS and obtaining approval for use. The contractor held a safety stand down to discuss proper procedures concerning the use of approved chemicals to close the finding. Ref: SCWI-8715-0008 Section 9.12 Item 1. SHEtrak closed # 102699











Weekly Safety Meeting

Project:	Sanitary Sewer Recap 80SSC018F0044
Location:	Stennis Space Center, Multiple Locations
Taula of the	Weeks SDS/Flamebles

Date: 5-08-2019

Attendees:	, Signature	Company
had Sillimin	Chris sitte	578
Tobas Hen Moss		5+5
Warlas moranor	Finds - Mount	5+5
13/tw/longton	Blanca le	5-5
La taxeniar	La Land	515
155 Hirran	July Willowen	575
box/anza	Alund Ing	Luckinbell
coff Kastner /	Litt Hart	Div Const
Rick Rodden	fle feddige	Di Coust.
Josep Slayter	Lifery stiffet	Lucking, !!
1 1	1/	

Discussed the new to have all material used at Stennis documented and used properly. Items in company or personal vehicles are subject to some documentation requirements



fety

Construction Safety Report: 13 May – 17 May 2019

Findings: 0

Level 1 Severity: 0

(Corrected on the spot)

Level 2 Severity: 0

(Corrective action documented)



Construction Safety Report: 20 May – 31 May 2019



Findings: 2

Level 1 Severity: 2

(Corrected on the spot)

— Wellness Center Expansion Project: On May 24, an improperly tagged and poorly inspected scaffold was discovered during a jobsite inspection. The following deficiencies were noted: 1) Scaffold frame sections were not connected utilizing required pins. 2) The space from scaffold frame system to wall was over the 18" maximum allowable distance. 3) The top platform scaffold access opening for entry/exit was placed on the opposite side of the ladder. 4) Scaffold system work platforms above 10 feet were missing required toe boards. These deficiencies were only permissible if annotated on a yellow scaffold tag (for cautionary use), vs the green tag which was in place. Ref: 29CFR1926.454 (b) (2). SHEtrak # 103331 Closed

<u>-High Pressure Gas Phase II Project:</u> On May 30, the contractor failed to place a properly rated fire extinguisher (20-B or greater) not less than 25 feet and no more than 75 feet from the flammable liquid storage tank.


Ref: 29CFR1926.152 (d)(2). SHEtrak # 103372 Closed

Level 2 Severity: 0

(Corrective action documented)






















Construction Safety Report: 27 May – 31 May 2019



Findings: 1

Level 1 Severity: 1

(Corrected on the spot)

<u>-High Pressure Gas Phase II Project:</u> On May 30, The contractor failed to place a not less than 20-B rated fire extinguisher not less than 25 feet and no more than 75 feet from the flammable liquid storage tank.

Ref: 29CFR1926.152 (d)(2). SHEtrak # 103372 Closed

Level 2 Severity: 0

(Corrective action documented)









Heat And Hydration situation:



On May 25th the Bastion Inspector was performing a construction safety site visit, he observed a contractor employee displaying signs of being overheated. The inspector took the employee to the job-site office trailer and where the employee was given water. The project superintendent kept the employee in the air conditioned office until it was determined that the employee could safely return to work. Several follow-up checks on the employee were made the remainder of the work day.

Closing Reminder: SSC VPP Re-certification the week of: June 10th through the 14th.



Contractors Mobile Cooling Station:







Questions/Discussion





http://constructionsafety.ssc.nasa.gov/