



Mission Success Starts With Safety



# Construction Safety

---

SSC Construction Inspection  
Safety Findings/Stats

June 2017



Mission Success Starts With Safety



# Contact Info:

NASA Safety

---

Donna Dubuisson

[donna.a.dubuisson@nasa.gov](mailto:donna.a.dubuisson@nasa.gov)

228-688-2663 phone

288-688-3701 fax

Jesse Lamonte

[jesse.m.lamonte@nasa.gov](mailto:jesse.m.lamonte@nasa.gov)

228-688-1422

228-688-2760 fax

Robert Simmers

[robert.e.simmers@nasa.gov](mailto:robert.e.simmers@nasa.gov)

228-688-1877

228-688-3701 fax

<http://constructionafety.ssc.nasa.gov/>



Mission Success Starts With Safety



# Contact Info:

BASTION/SACOM Safety

---

Donald Smith, CHST

[donald.g.smith-1@nasa.gov](mailto:donald.g.smith-1@nasa.gov)

228-688-1085 phone

228-688-3701 fax

Mark Bridenbeck, TES

[mark.a.bridenbeck@nasa.gov](mailto:mark.a.bridenbeck@nasa.gov)

228-688-1732 phone

228-688-3701 fax

John Lindsay, CSP

[john.d.lindsay@nasa.gov](mailto:john.d.lindsay@nasa.gov)

228-688-2557 phone

288-688-3503 fax


Chris Davis, ASP

[christopher.m.davis-1@nasa.gov](mailto:christopher.m.davis-1@nasa.gov)

225-802-6273 phone

288-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



# Construction Safety Report: 01 Jun – 09 Jun 2017

## Findings Total: 4

## Serious: 1

- **B2 STE Phase I**: Contractor failed to have on the required fall protection safety harness while utilizing a scaffold with an exposed fall area through an unprotected open side. Ref: 29CFR1926.501(b)(1) SHEtrak Closed

## Other than Serious: 3

- **HPG**: Contractor was using a lift device with a broken safety latch on the hook. Defective rigging material shall be removed from service. 29CFR1926.251 item (a)(1) SHEtrak closed
- **B2 STE Phase I**: Contractor failed to place required personal LOTO lock and tag on the gang hasp prior to performing elevated work above the level 7 rolling deck. Ref: 29CFR1910.147(f)(3)(ii)(d) SHEtrak Closed
- **Bascule Bridge**: Contractor failed to label the outside of the sprayer with the name of the contents within the pump sprayer. SCWI-8715-0008 Section 9.11 Item 3. SHEtrak Closed

## Mishaps / Close Calls: 0



# Construction Safety Findings:







Mission Success Starts With Safety




# Construction Safety Findings:





# Construction Safety Findings:






Mission Success Starts With Safety



# Construction Safety Findings:







# Construction Safety Report:

## 12 Jun – 16 Jun 2017

---

### Findings Total: 3


### Serious: 1

- **HPG Fab Tent:** Contractor failed to provide positive means of pinning the air connection fitting and attaching the hose whip-check to prevent accidental disconnect of the pneumatic air supply. 29CFR1926.302 (b)(1) SHEtrak Closed


### Other than Serious: 2


- **B2 STE Phase I:** Contractor failed to follow construction site PPE requirements by not wearing the proper safety eye wear. Ref: SCWI-8715-0008 Section 9.3 SHEtrak Closed
- **8100 Lab Expansion:** Contractor failed to have required hot work permit or activity hazard analysis present on site. Ref: SCWI-8715-0008 Section 9.4 (5) SHEtrak Closed

### Mishaps / Close Calls: 0



# Construction Safety Report: 12 Jun – 16 Jun 2017





# Construction Safety Report: 19 Jun – 23 Jun 2017

---

**Findings Total: 0**

**Serious: 0**

**Other than Serious: 0**

**Mishaps / Close Calls: 0**



# Construction Safety Report: 26 Jun – 30 Jun 2017

---

**Findings Total: 0**

**Serious: 0**

**Other than Serious: 0**

**Mishaps / Close Calls: 0**



Questions?

<http://constructionsafety.ssc.nasa.gov/>