



Mission Success Starts With Safety



# Construction Safety

---

SSC Construction Inspection  
Safety Findings/Stats

June 2018



Mission Success Starts With Safety



# Contact Info:

NASA Safety

---

Mike Rewis

[mike.j.rewis@nasa.gov](mailto:mike.j.rewis@nasa.gov)

228-688-2663

288-688-3701 fax

Elizabeth Calantoni

[elizabeth.calantoni@nasa.gov](mailto:elizabeth.calantoni@nasa.gov)

228-688-1804

228-688-2760 fax


Donna Dubuisson

[donna.a.dubuisson@nasa.gov](mailto:donna.a.dubuisson@nasa.gov)

228-688-1167

228-688-3701 fax

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



# Contact Info:

BASTION/SACOM Safety

---

Donald Smith, CHST

[donald.g.smith-1@nasa.gov](mailto:donald.g.smith-1@nasa.gov)

228-688-1085 phone

228-688-3701 fax

Mark Bridenbeck, TES

[mark.a.bridenbeck@nasa.gov](mailto:mark.a.bridenbeck@nasa.gov)

228-688-1732 phone

228-688-3701 fax

John Lindsay, CSP

[john.d.lindsay@nasa.gov](mailto:john.d.lindsay@nasa.gov)

228-688-2557 phone

288-688-3503 fax


George Turner

[george.turner@nasa.gov](mailto:george.turner@nasa.gov)

228-688-2445 phone

288-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



# Construction Safety Report: 01 June – 09 June 2018

---


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 11 June – 16 June 2018

---


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 18 June – 23 June 2018

---


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 25 Jun – 30 Jun 2018

---

**Findings: Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)


**Mishaps: 0 / Close Calls: 1**

**B-2 Fire-X/HPIW Restoration:** A section of 48" HPIW piping was being delivered via the B2 derrick crane. Workers were on the southeast platform to install the pipe. There is a hole in the grating of sufficient size for a person to fall in the immediate vicinity of the pipe being installed. In addition, this hole is adjacent to an opening without handrails that leads to a substantial drop. Neither the hole nor the opening had protective measures against falls. Hazardous condition: Several of the personnel working within a few feet of this opening were not using fall protection. A fall into the hole or through the opening would likely have resulted in a serious injury. (CCRS 18-037)



Previously unprotected area





# Questions/Discussion

---



<http://constructionsafety.ssc.nasa.gov/>