SSC Construction Inspection Safety findings

September, 2008

Prepared/presented by: Daryl Kosturock, Safety Inspector Bastion Technologies

Contact Info:

Buddy Newbold buddy.newbold-1@nasa.gov 228-688-3152 phone 288-688-3701 fax

Daryl Kosturock daryl.kosturock-1@nasa.gov 228-688-3641 phone 228-688-3701 fax

http://constructionsafety.ssc.nasa.gov/

Construction Safety Findings: 29 August – 04 September 2008 Findings Total: 0 - Serious Findings: 0 - Less than Serious Findings: 0 Note: SSC was closed, all but one day of this reporting period due to Hurricane Gustav. Mishaps: 0 / Close Calls: 1 Close Calls: 1 Contractor damaged a guy-wire on an electric pole by hitting it with the bucket of an excavator.

Construction Safety Findings: 05–11 September 2008

Findings Total: 5 - Serious Findings: 1

- Electrical: 1
 - Several locations throughout newly constructed building with energized wires exposed from receptacles and temporary lights. 29 CFR 1926.405

- Less than Serious Findings: 4

- Ladders: 1
 - Two different electricians improperly using stepladders. One was standing on top of a ladder and another was standing on a closed ladder that was leaned against a wall.
 29 CFR 1926.1053
- PPE: 1
 - Employee working in a construction area was not wearing a hard hat. SSP 8715-0001 (3.5.3)

• Other: 2

- Several employees working near unprotected rebar, exposed to impalement hazards.
 29 CFR 1926.701
- Contractor failed to submit a traffic control plan and off-site mobile crane documentation prior to bringing the crane on site and using it on the road, with traffic being diverted around it. Spec doc 20000-GM30 Section 01 35 30, paragraph 3.5

Mishaps: 0 / Close Calls: 0

Construction Safety Findings: 12–18 September 2008

Findings Total: 0

- Serious Findings: 0

- Less than Serious Findings: 0

Mishaps: 0 / Close Calls: 0

Construction Safety Findings: 19-25 September 2008 Findings Total: 2 - Serious Findings: 0 - Less than Serious Findings: 2 Welding and Cutting: 1 The contractor left a cart with oxygen and acetylene cylinders stored together in the lay-down yard over the weekend. 29 CFR 1926.350(a)(10) Haz-Com: 1 Fuel can on site not properly labeled 29 CFR 1926.59 / 1910.1200(f) Mishaps: 0 / Close Calls: 1


Close Call: 1

Contractor used a forklift to move a semi-trailer.

Construction Safety Findings: 26-30 September 2008 Findings Total: 1 - Serious Findings: 0 - Less than Serious Findings: 1 • Other: 2 Several employees working near unprotected rebar, exposed to impalement hazards. 29 CFR 1926.701 Mishaps: 1 / Close Calls: 1 Mishap: 1 Contractor hit a four inch water line while digging a hole. Close Call: 1

Contractor damaged a four inch water line when the side of an open excavation collapsed, causing the line to break.

2008 Construction Safety Findings by category:




September / 8

Fall Protection Electrical
 PPE
 Housekeeping Ladders
 Other



Construction Safety Findings by category:

35



CY 2008 Total

Fall Protection Electrical Trenching
 PPE Housekeeping Ladders
 Other




Summary

Total Findings: 8
Serious Findings: 1
Less than serious Findings: 7
Close Calls: 3
Mishaps: 1
Injuries: 0

Safety

The following is a demonstration of why a competent person should be in charge of selecting the appropriate fall protection!





*Complacency will hurt you when you least expect it.

