



Mission Success Starts With Safety



Construction Safety

SSC Construction Inspection
Safety Findings/Stats

November 2018



Mission Success Starts With Safety



Contact Info:

NASA Safety

Mike Rewis

mike.j.rewis@nasa.gov

228-688-2663

288-688-3701 fax

Elizabeth Calantoni

elizabeth.calantoni@nasa.gov

228-688-1804

228-688-2760 fax

Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-1167

228-688-3701 fax

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



Contact Info:

BASTION/SACOM Safety

Donald Smith, CHST

donald.g.smith-1@nasa.gov

228-688-1085 phone

228-688-3701 fax

Mark Bridenbeck, TES

mark.a.bridenbeck@nasa.gov

228-688-1732 phone

228-688-3701 fax

John Lindsay, CSP

john.d.lindsay@nasa.gov

228-688-2557 phone

288-688-3503 fax


Will Davis

william.b.davis@nasa.gov

228-688-3193 phone

228-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



Construction Safety Report: 01 November – 09 November 2018

Findings: 1

Level 1 Severity : 1

(Corrected on the spot)

HPG Phase II: On Friday, 02 November, A contractor failed to complete the required daily operator inspection form for a piece of equipment prior to starting work. Ref: 29CFR1926.601 (b) (14) SHEtrak # 90034. Closed

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0




Construction Safety Findings: Inspection Period: 10.29.18 – 11.02.18


Inspector: Dylan Farmer

Week Beginning: 10-29-18/11-

*...nally tested and visually inspected each day. The designated inspector
... box when an item passes inspection. Leave the box empty and note a
... Immediately notify the Foreman of deficiencies. The Foreman will forwa
... ety Dept. at the end of each week.*

	Mon	Tue	Wed	Thu	Fri	Sat	Sun	Maintenance Needed
	/							
ins	/							
g Prts.	/							
Parts clean	/							
ual	/							





Construction Safety Report: 12 November – 16 November 2018

Findings:


Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Report: 19 November – 23 November 2018

Findings: 0

Level 1 Severity : 0


(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 1

Building 4210: On 11-20-18, At approximately 1530, an unmarked 1-1/4" copper water line was struck at B4210. This 1-1/4" copper waterline serves the exterior building spigots and has been temporarily isolated while S-3 made the repair. No other building systems were affected. The excavator pulled the line from the elbow approximately 15' south of the excavation where the strike occurred. A SSC form 1627 was generated.



Construction Safety Findings:





Construction Safety Report: 26 November – 30 November 2018

Findings:


Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)


Mishaps: 0 / Close Calls: 0




NASA/SSC Construction Safety Status



**Total Case Incidence Rate (TCIR)/
Days Away Restricted Transfer (DART)/
Lost Time Incidence Rate**





Questions/Discussion



<http://constructionsafety.ssc.nasa.gov/>