

Construction Safety

SSC Construction Inspection Safety Findings/Stats

December 2016



Contact Info:



NASA Safety

Donna Dubuisson donna.a.dubuisson@nasa.gov

> 228-688-2663 phone 288-688-3701 fax

Jesse Lamonte jesse.m.lamonte@nasa.gov 228-688-1422 228-688-2760 fax Kathy Cooper kathy.a.cooper@nasa.gov 228-688-1747 228-688-3701 fax

http://constructionsafety.ssc.nasa.gov/



Contact Info:



BASTION/SACOM Safety

Donald Smith, CHST donald.g.smith-1@nasa.gov 228-688-1085 228-688-3701 fax

Mark Bridenbeck mark.a.bridenbeck@nasa.gov 228-688-1732 228-688-3701 fax

John Lindsay, CSP john.d.lindsay@nasa.gov 228-688-2557 phone 288-688-3503 fax

Chris Davis, ASP christopher.m.davis-1@nasa.gov 225-802-6273 phone 288-688-3503 fax

http://constructionsafety.ssc.nasa.gov/



Construction Safety Report: 01 December – 03 December 2016



Findings Total: 0

Serious: 0

Other than Serious: 0

Mishaps/Close Calls: 1

<u>B2 WP3:</u>On December 2, at about 16:30, an employee was using a buffing wheel grinder cleaning grout around an iron beam, when the grinder kicked back and slightly grazed him above the right knee. The employee's injury was treated with a small band aid. (NMIS Close Call 16-101868)





Construction Safety Findings:









Construction Safety Report: 5 – 10 December 2016

Findings Total: 2 Serious: 0


Other than Serious: 2

- <u>B2 WP3</u>: The contractor failed to properly place the GFCI at the power source outlet.
 29CFR1926.404 (b)(1)(ii)
- <u>Tarmac:</u> Inspector observed individual drilling concrete dry, wearing a half mask respirator with P100 cartridges without the required fit test and written respiratory protection plan. When the safety manager asked the supervisor if they had a plan and fit test, he stated no. Work was stopped 29CFR1926.134(C)(1)





Construction Safety Findings:







Construction Safety Findings:





Construction Safety Report:

12 December–17 December 2016

Findings Total: 3

Serious: 1

 <u>B2 WP4</u>: A contractor was utilizing two separate scaffolds in the same day without having the required inspections and tags prior to use. Reference: SCWI8715-0001 Paragraph 3.16 Item a


Other than Serious: 2

- <u>B2 WP4:</u> Contractor failed to properly utilize GFCI at the power source outlet. Reference: 29CFR1926.404 (b)(1)(ii)
- <u>HVAC ATTC:</u> Contractor failed to properly utilize GFCI at the power source outlet. Reference: 29CFR1926.404 (b)(1)(ii)


Construction Safety Findings: 12 – 17 December 2016



Construction Safety Findings: 12 – 17 December 2016



Construction Safety Findings: 12 – 17 December 2016







Construction Safety Report: 19 December – 24 December 2016

Findings Total: 0

Serious: 0

Other than Serious: 0





Construction Safety Report: 27 December – 30 December 2016

Findings Total: 0

Serious: 0

Other than Serious: 0





Don't Forget: February 1st OSHA 300 gets posted



Questions?

http://constructionsafety.ssc.nasa.gov/



Santa Recycles!

CV (



Have a Safe month!