



Mission Success Starts With Safety



Construction Safety

SSC Construction Inspection
Safety Findings/Stats

February 2018



Mission Success Starts With Safety



Contact Info:

NASA Safety

Mike Rewis

mike.j.rewis@nasa.gov

228-688-2663

288-688-3701 fax

Elizabeth Calantoni

elizabeth.calantoni@nasa.gov

228-688-1804

228-688-2760 fax

Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-1167

228-688-3701 fax

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



Contact Info:

BASTION/SACOM Safety

Donald Smith, CHST

donald.g.smith-1@nasa.gov

228-688-1085 phone

228-688-3701 fax

Mark Bridenbeck, TES

mark.a.bridenbeck@nasa.gov

228-688-1732 phone

228-688-3701 fax

John Lindsay, CSP

john.d.lindsay@nasa.gov

228-688-2557 phone

288-688-3503 fax


George Turner

george.turner@nasa.gov

228-688-2445 phone

288-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



Construction Safety Report: 01 Feb – 10 Feb 2018


Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Report: 12 Feb – 17 Feb 2018

Level 1 Severity : 1

(Corrected on the spot)

- **WP3** - Contractor failed to use required ground fault circuit interrupter.
Ref: 29CFR1926.404 (b) (1) (ii). Corrected on the spot. SHEtrak Closed. ID# 84837

Level 2 Severity : 0


(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Findings:





Construction Safety Report: 19 Feb – 24 Feb 2018


Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Mission Success Starts With Safety



Questions/Discussion



<http://constructionsafety.ssc.nasa.gov/>