



Construction Safety

SSC Construction Inspection Safety Findings/Stats

February 2019



Contact Info:



NASA Safety

Mike Rewis

mike.j.rewis@nasa.gov

228-688-2663

288-688-3701 fax

Elizabeth Calantoni

elizabeth.calantoni@nasa.gov

228-688-1804

228-688-2760 fax

Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-1167

228-688-3701 fax

http://constructionsafety.ssc.nasa.gov/



Contact Info:



BASTION/SACOM Safety

Donald Smith, CHST donald.g.smith-1@nasa.gov 228-688-1085 phone 228-688-3701 fax

John Lindsay, CSP john.d.lindsay@nasa.gov 228-688-2557 phone 288-688-3503 fax Mark Bridenbeck, TES

mark.a.bridenbeck@nasa.gov

228-688-1732 phone

228-688-3701 fax

Will Davis
william.b.davis@nasa.gov
228-688-3193 phone
228-688-3503 fax

http://constructionsafety.ssc.nasa.gov/



Construction Safety Report: 01 February – 08 February 2019



Findings: 1

Level 1 Severity: 1

(Corrected on the spot)

<u>Fitness Center Expansion:</u> On 02-01-19, a contractor failed to complete a daily equipment inspection prior to starting work. Ref: 29CFR1926.601 (b)(14) SHEtrak ID # 91238. Closed

Level 2 Severity: 0

(Corrective action documented)

Mishaps: 1 / Close Calls: 0

Natural Gas Project: The contractor was performing an excavation to locate an underground natural gas valve at the Trent Lott Parkway entrance to the 8100 area and struck a 1.5 inch branch line off the 10 inch main. As a precautionary measure, traffic was interrupted on TL Parkway. The shops responded and cut the gas off, installed a steel plug, and then re-energized the main line. Permanent repairs were completed. SSC 1627 and NMIS reports have been submitted.



Construction Safety Report:

01 February – 08 February 2019







Construction Safety Report: 04 February – 08 February 2019



Findings: 0

Level 1 Severity: 0 (Corrected on the spot)

Level 2 Severity: 0 (Corrective action documented)

Mishaps: 1 / Close Calls: 0

<u>Electrical Repairs Canal Lock Controls</u>: During probing and excavating activities while looking for a power line (which had been identified by S-3 utility locates but was not on the drawings,) the contractor struck a 2 inch conduit housing a 110volt electrical line and several communication camera video lines. Securadyne responded and revealed that though the conduit was broken, the internal wires were not severed. There was no interruption of power or video camera capabilities. The General Contractors (GC) electrical contractor made repairs and Securadyne verified repairs were acceptable. The case was reported in NMIS and the GC submitted an SSC Form 1627.





Construction Safety Findings:





Construction Safety Report:



11 February – 15 February 2019

Findings: 0

Level 1 Severity: 0

(Corrected on the spot)

Level 2 Severity: 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Safety

Construction Safety Report: 18 February – 22 February 2019

Findings:

Level 1 Severity: 0

(Corrected on the spot)

Level 2 Severity: 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Report: 25 February – 28 February 2019



Findings: 0

Level 1 Severity: 0

(Corrected on the spot)

Level 2 Severity: 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0

OSHA Top Ten Violations 2018:

- 10. Personal Protective and Lifesaving Equipment—Eye and Face Protection: 1926.102, with
- 1,536 violations
- 9. Machine Guarding: 1910.212, with 1,972 violations
- 8. Fall Protection—Training Requirements: 1926.503, with 1,982 violations
- 7. Powered Industrial Trucks: 1910.178, with 2,294 violations
- 6. Ladders: 1926.1053, with 2,812 violations
- 5. Lockout/ Tag out: 1910.147, with 2,944 violations
- 4. Respiratory Protection: 1910.134, with 3,118 violations
- 3. Scaffolds—General Requirements: 1926.451, with 3,336 violations
- 2. Hazard Communication: 1910.1200, with 4,552 violations
- 1. Fall Protection—General Requirements: 1926.501, with 7,720 violations





2019 Follow Up Reminders:

- Review all SDS's: Compare electronic data sheets to see if there have been any updates Cover letter to state 2019 annual review was completed
- ➤ All fire extinguishers to have 2019 annual service inspection and if due, 6 year maintenance
- Review any or all Forklift licenses for any 2019 expiration
- > Up date LOTO training and certs for 2019
- Up date Confined Space training and certs for 2019
- Review staff for Gulf Coast Safety Council refresher training. (2 years from date of issue)



Questions/Discussion





http://constructionsafety.ssc.nasa.gov/