



Mission Success Starts With Safety



# SSC Construction Contractor Safety Meeting

May 7, 2020



# Contact Info:

NASA Safety

---

Matthew Scott

[matthew.r.scott@nasa.gov](mailto:matthew.r.scott@nasa.gov)

228-688-1537

Construction Safety

Donna Dubuisson

[donna.a.dubuisson@nasa.gov](mailto:donna.a.dubuisson@nasa.gov)

228-688-1167

Construction Safety

Elizabeth Calantoni

[elizabeth.calantoni@nasa.gov](mailto:elizabeth.calantoni@nasa.gov)

228-688-1804

B2 Test Stand

Neil Toupin

[neil.s.toupin@nasa.gov](mailto:neil.s.toupin@nasa.gov)

228-688-1109

A1 Test Stand

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



# Contact Info:

BASTION/SACOM Safety

---

Donald Smith, CHST

[donald.g.smith-1@nasa.gov](mailto:donald.g.smith-1@nasa.gov)

228-688-1085 phone

228-234-0639 Cell

Mark Bridenbeck, TES

[mark.a.bridenbeck@nasa.gov](mailto:mark.a.bridenbeck@nasa.gov)

228-688-1732 phone

228-313-0188 Cell

John Lindsay, CSP

[john.d.lindsay@nasa.gov](mailto:john.d.lindsay@nasa.gov)

228-688-2557 phone

288-688-3503 fax


Will Davis

[william.b.davis@nasa.gov](mailto:william.b.davis@nasa.gov)

228-688-3193 phone

228-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>




# Construction Safety

---

SSC Construction Inspection  
Safety Findings/Stats

March 2020



# Construction Safety Report: 01 March – 07 March 2020

---

**Findings: 0**


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 08 March – 14 March 2020

---

## Findings: 1

### Level 1 Severity : 1

(Corrected on the spot)


•**Sanitary Sewer Recapitalization Project:** On March 10, 2020, two contractors were observed riding in their company vehicle without wearing seatbelts. Ref: SPR 1600.1 (4.2 Item 5f). Drivers and passengers of all vehicles operating at SSC shall use seat belts while the vehicle is in motion or in operation on SSC property. It is the duty of the operator of a vehicle to ensure that seat belts are properly fastened prior to placing the vehicle in motion.

SHetrak Id # 140773. Finding Closed.

### Level 2 Severity : 0

(Corrective action documented)

## Mishaps: 0 / Close Calls: 0



# Construction Safety Report: 15 March – 21 March 2020

---

**Findings: 0**


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 22 March – 31 March 2020

---

**Findings: 0**

**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**






# Construction Safety

---

SSC Construction Inspection  
Safety Findings/Stats


April 2020



# Construction Safety Report: 01 April – 30 April 2020

---

**There was no monthly contractor meeting due to the Covid-19 virus outbreak and SSC closure.**



## Discussion Topics

---

- **Monthly Mishap Exposure Report**
- **SSC Covid-19 Safe-at-Work Protocol**

# Questions?