



Mission Success Starts With Safety



Construction Safety

SSC Construction Inspection
Safety Findings/Stats

July 2017



Mission Success Starts With Safety



Contact Info:

NASA Safety

Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-2663

288-688-3701 fax

Jesse Lamonte

jesse.m.lamonte@nasa.gov

228-688-1422

228-688-2760 fax

Robert Simmers

robert.e.simmers@nasa.gov

228-688-1877

228-688-3701 fax

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



Contact Info:

BASTION/SACOM Safety

Donald Smith, CHST

donald.g.smith-1@nasa.gov

228-688-1085 phone

228-688-3701 fax

Mark Bridenbeck, TES

mark.a.bridenbeck@nasa.gov

228-688-1732 phone

228-688-3701 fax

John Lindsay, CSP

john.d.lindsay@nasa.gov

228-688-2557 phone

288-688-3503 fax


Chris Davis, ASP

christopher.m.davis-1@nasa.gov

225-802-6273 phone

288-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



Construction Safety Report:

03 Jul – 07 Jul 2017


Findings Total: 1

Serious: 0

Other than Serious: 1

- **STE Phase I:** Two separate Argon gauges had visible signs of damage i.e.(Bent damaged internal components and missing gauge protective face covers). Both regulator units were connected to separate active Argon bottle banks. 29CFR1926.350 (h) SHEtrak I.D. 93474. Open. Sub-contractor disconnected and removed gauges. General contractor requested a reoccurrence preventive action plan from their subcontractor

Mishaps / Close Calls: 0



Construction Safety Findings:






Construction Safety Report: 10 Jul – 14 Jul 2017

Findings Total: 0

Serious: 0

Other than Serious: 0

Mishaps / Close Calls: 0




Construction Safety Report: 17 Jul – 21 Jul 2017

Findings Total: 0

Serious: 0

Other than Serious: 0

Mishaps / Close Calls: 0



Construction Safety Report:

24 Jul – 31 Jul 2017


Findings Total: 2

Serious: 2

- **B2 STE Phase I**: Contractor violated confined space permit requirements by failing to ensure all procedures and practices were in place before entry was allowed. Such as: No attendant present, no entrants signed in, no atmospheric testing with continuous monitoring. Ref: SCWI-8715-0004 Section 4.5.2 Item (h) SHEtrak Closed by retraining. ID # 94364
- **8100 Lab Expansion**: A contractor employee was using a scaffold without first completing the required scaffold inspection and completing the tag sign-off. The infraction was reported to the General Contractor where they took administrative corrective action.
Ref: 29CFR1926.451 (f) (3) Closed. I.D. # 81028

Other than Serious: 0

Mishaps / Close Calls: 0



Questions/Discussion



<http://constructionsafety.ssc.nasa.gov/>