



Mission Success Starts With Safety



# Construction Safety

---

SSC Construction Inspection  
Safety Findings/Stats

July 2019



Mission Success Starts With Safety



# Contact Info:

NASA Safety

---

Mike Rewis

[mike.j.rewis@nasa.gov](mailto:mike.j.rewis@nasa.gov)

228-688-2663

288-688-3701 fax

Elizabeth Calantoni

[elizabeth.calantoni@nasa.gov](mailto:elizabeth.calantoni@nasa.gov)

228-688-1804

228-688-2760 fax


Donna Dubuisson

[donna.a.dubuisson@nasa.gov](mailto:donna.a.dubuisson@nasa.gov)

228-688-1167

228-688-3701 fax

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



# Contact Info:

BASTION/SACOM Safety

---

Donald Smith, CHST

[donald.g.smith-1@nasa.gov](mailto:donald.g.smith-1@nasa.gov)

228-688-1085 phone

228-688-3701 fax

Mark Bridenbeck, TES

[mark.a.bridenbeck@nasa.gov](mailto:mark.a.bridenbeck@nasa.gov)

228-688-1732 phone

228-688-3701 fax

John Lindsay, CSP

[john.d.lindsay@nasa.gov](mailto:john.d.lindsay@nasa.gov)

228-688-2557 phone

288-688-3503 fax

Will Davis

[william.b.davis@nasa.gov](mailto:william.b.davis@nasa.gov)

228-688-3193 phone

228-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



# Construction Safety Report: 01 July – 05 July 2019

---

## Findings: 1

### Level 1 Severity : 1


#### (Corrected on the spot)

- **B2 Restoration:** On July 02, at approx. 0900, A contractor was observed utilizing a suspended scaffold on level 23 B-2 Test Stand without first completing the required scaffold inspection and tag sign-off.  
Ref: 29CFR1926.451 (F) (3). Employee removed himself from the system until it was properly inspected. Closed. SHEtrak ID # 104151

### Level 2 Severity : 0

(Corrective action documented)


**Mishaps: 0 / Close Calls: 0**



# Construction Safety Findings:

6-14-11	B. Dunaway
6-17	B. Dunaway
6-19	S. Hammett
6-20	B. Dunaway
6-21	S. Hammett
6-28	S. Hammett
7-1	B. Dunaway

©GLADTAGS (225) 490-4242 NYL-901-249



# Construction Safety Report: 08 July – 12 July 2019

---

**Findings: 0**


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 15 July – 19 July 2019

---

**Findings: 0**


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**



# Construction Safety Report: 22 July – 26 July 2019

---

**Findings: 0**

**Level 1 Severity : 0**

(Corrected on the spot)


**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 1**


**Nordberg Bypass: On July 24, during excavation activities near the Bldg 4400 HPIW reservoir, a one inch electrical conduit was struck.  
NMIS Close Call 19-101021**





# Construction Safety Findings:





# Construction Safety Report: 29 July – 31 July 2019

---

**Findings: 0**


**Level 1 Severity : 0**

(Corrected on the spot)

**Level 2 Severity : 0**

(Corrective action documented)

**Mishaps: 0 / Close Calls: 0**




[www.NanoLokEdgeRecall.com](http://www.NanoLokEdgeRecall.com)

## Stop Use & Recall Notice

### IMMEDIATE ACTION REQUIRED

# 3M™ DBI-SALA® Nano-Lok™ *edge* and Wrap Back Twin-Leg Self Retracting Lifelines





# August

---

- **August is the hottest month of the summer, please remember to document heat and hydration on every AHA / SPA until September 30<sup>th</sup> 2019**



# Questions/Discussion

---



<http://constructionsafety.ssc.nasa.gov/>