



Construction Safety

SSC Construction Inspection Safety Findings/Stats

September 2014



Mission Success Starts With Safety

Contact Info:

NASA Safety



Mike Rewis

mike.j.rewis@nasa.gov

228-688-2663 phone

288-688-3701 fax

Robert Southers
robert.l.southers@nasa.gov
228-688-1324 phone
228-688-3701 fax

Kathy Cooper
kathy.a.cooper@nasa.gov
228-688-1747
228-688-3701 fax

http://constructionsafety.ssc.nasa.gov/





Contact Info:



BASTION/FOSC Safety

Daryl Kosturock, CHST daryl.kosturock-1@nasa.gov 228-688-3641 phone 228-688-3701 fax

Donald Smith, CHST donald.g.smith-1@nasa.gov 228-688-1085 228-688-3701 fax

John Lindsay, CSP john.d.lindsay@nasa.gov 228-688-2557 phone 288-688-3503 fax Robert Necaise
robert.j.necaise@nasa.gov
228-688-2049 phone
288-688-3503 fax

Darrin Steber

darrin.r.steber@nasa.gov

228-688-2502 phone

288-688-3503 fax

http://constructionsafety.ssc.nasa.gov/



Construction Safety Findings: 2-5 September 2014



Findings Total: 1

-Serious Findings: 0

-Less than Serious Findings: 1

1. Truck-Crane bed is in need of wood deck repair/replacement. 29CFR1926. 601(14)

Mishaps / Close Calls: 0









Construction Safety Findings: 8-12 September 2014

Findings Total: 0

-Serious Findings: 0

-Less than Serious Findings: 0

Mishaps / Close Calls: 0



Construction Safety Findings: 15-19 September 2014



Findings Total: 1

-Serious Findings: 0

-Less than Serious Findings: 1

1. Worker found on site with improper foot-wear for a construction area. SCWI 8715-0002 section 7.1(e)(2)

Mishaps / Close Calls: 2

Mishap: 1

1. A worker had an unknown item, believed to be dirt, item enter the left eye causing irritation. The worker went to an off-site clinic for treatment and received an antibiotic perscription, making this case an OSHA Recordable or NASA Type D mishap.


Close Call: 1

1. A worker became ill after being exposed to chlorine gas while cutting into the existing water line. The SSC Fire Department responded and determined the scene was safe and detected a minimal presence of chlorine gas vapors, well under the Permisable Exposure Limit. The worker was transported to the SSC clinic and received a precautionary decontamination. The worker was also evaluated and released to return to work without any medical treatment or First Aid being performed, making this a Close Call.



STATE OF STREET

Construction Safety Findings: 15-19 September 2014





Construction Safety Findings: 22-25 September 2014



Findings Total: 5

-Serious Findings: 0

-Less than Serious Findings: 5

- 1. Forklift operator failed to complete a forklift daily inspection prior to use. SCWI-8715-0008 section 6.8.3.
- 2. Unauthorized tape repair of an extension cord, 29CFR 1926.405 (g)(2)(iii)
- 3. Improper strain relief on an electrical cord connection, 29CFR1926.405 (g)(2)(iv)
- 4. Workers in a five (5) foot deep excavation without means of egress, 29CFR 1926.651(c)(2)
- 5. Workers in an excavation where the spoil pile was not set back at least two (2) feet, 29CFR 1926.651(j)(2)

Mishaps / Close Calls: 1

Close Call: 1


1. While rearranging a stack of slide rail beams, a worker's left wrist brushed against a sharp piece metal causing an abrasion. The worker went to construction site office trailer and received first aid treatment.





Construction Safety Findings: 22-25 September 2014










SSC Construction Metrics

- For the month of August:
 - No NASA Direct Construction cases of type D severity or greater.







Construction Safety

Questions?

http://constructionsafety.ssc.nasa.gov/





Construction Safety

