



Construction Safety

SSC Construction Inspection
Safety Findings/Stats

March 2020

**This meeting has been cancelled
Due to the COVID-19 Outbreak and
Closure of SSC**



Contact Info:

NASA Safety

Matthew Scott

matthew.r.scott@nasa.gov

228-688-1537

Construction Safety

Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-1167

Construction Safety

Elizabeth Calantoni

elizabeth.calantoni@nasa.gov

228-688-1804

B2 Test Stand

Neil Toupin

neil.s.toupin@nasa.gov

228-688-1109

A1 Test Stand

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



Contact Info:

BASTION/SACOM Safety

Donald Smith, CHST

donald.g.smith-1@nasa.gov

228-688-1085 phone

228-234-0639 Cell

Mark Bridenbeck, TES

mark.a.bridenbeck@nasa.gov

228-688-1732 phone

228-313-0188 Cell

John Lindsay, CSP

john.d.lindsay@nasa.gov

228-688-2557 phone

288-688-3503 fax


Will Davis

william.b.davis@nasa.gov

228-688-3193 phone

228-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



Construction Safety Report: 01 March – 07 March 2020

Findings: 0


Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Report: 08 March – 14 March 2020

Findings: 1

Level 1 Severity : 1

(Corrected on the spot)


•**Sanitary Sewer Recapitalization Project:** On March 10, 2020, two contractors were observed riding in their company vehicle without wearing seatbelts. Ref: SPR 1600.1 (4.2 Item 5f). Drivers and passengers of all vehicles operating at SSC shall use seat belts while the vehicle is in motion or in operation on SSC property. It is the duty of the operator of a vehicle to ensure that seat belts are properly fastened prior to placing the vehicle in motion.

SHetrak Id # 140773. Finding Closed.

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Report: 15 March – 21 March 2020

Findings: 0


Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0



Construction Safety Report: 22 March – 31 March 2020

Findings: 0

Level 1 Severity : 0

(Corrected on the spot)

Level 2 Severity : 0

(Corrective action documented)

Mishaps: 0 / Close Calls: 0