



Construction Safety

SSC Construction Inspection Safety Findings/Stats

August 2012







Contact Info:

NASA/BASTION/FOSC

Mike Rewis

mike.j.rewis@nasa.gov

228-688-2663 phone

288-688-3701 fax

Daryl Kosturock
daryl.kosturock-1@nasa.gov
228-688-3641 phone
228-688-3701 fax

Ethan Calder ethan.w.calder@nasa.gov 228-688-2049 phone 288-688-3503 fax





Contact Info:

A-3 Test Stand

Robert Gargiulo, A-3 Chief Safety Officer

robert.f.gargiulo@nasa.gov

228-688-3842 phone

228-688-3701 fax

Jim Deschenes

james.e.deschenes@nasa.gov

228-688-1837 phone

228-688-7619 fax

Donald Smith

donald.g.smith-1@nasa.gov

228-688-1085

228-688-3701 fax

James Gordon

james.g.gordon@nasa.gov

228-688-2794 phone

228-688-7619 fax

James Hancock

james.r.hancock@nasa.gov

228-688-1093 phone



Construction Safety Findings: 30 July-03 August 2012



Findings Total: 1

-Serious Findings: 0

-Less than Serious Findings: 1

1. A worker was observed performing torch cutting operations without proper eye/face PPE. The worker was using a clear face shield and eye wear not approved for welding/cutting activities. Closed /corrected on the spot.

Mishaps / Close Calls: 1

-Close Call: 1

1. An employee was concerned that a piece of construction equipment entered the north gate through the northbound lanes, against traffic. Case is under investigation.



Construction Safety Findings: 06-10 August 2012



Findings Total: 1

-Serious Findings: 0

-Less than Serious Findings: 1

1. A worker was operating a forklift without proof of training. Other workers were found with insufficient, "in-house" training. Contractor submitted their forklift training and certification for LDE approval and retrained employees on site.

Mishaps / Close Calls: 0



Construction Safety Findings: 13-17 August 2012



Findings Total: 0

-Serious Findings: 0

-Less than Serious Findings: 0

Mishaps / Close Calls: 1

-Close Call: 1

1. A concerned driver on SSC reported: "Since the new lane has been paved on Trent Lott Parkway, there has been a few unaware vehicles entering the closed road because there are no barricades or notices posted." This case is under investigation.



Construction Safety Findings: 20-24 August 2012



Findings Total: 1

-Serious Findings: 0

-Less than Serious Findings: 1

 Site Safety found a worker wearing personal fall arrest gear that had a damaged snap-hook at the base of the lanyard. The hook was bent, causing the gate and locking mechanism to not function properly. The worker was not tied-off during this inspection. The harness was destroyed and replaced.

Mishaps / Close Calls: 1

-Close Call: 1

1. A U.S. Army Corps of Engineers (USACE) contractor working on a duct bank installation for NCCIPS operated an excavator improperly, causing it to become unstable and partially fall into the excavation. There was no property damage or injuries. Operations at this site were shut down by USACE personnel and the incident is under investigation.



Construction Safety Findings: 27-31 August 2012



Findings Total: 0

-Serious Findings: 0

-Less than Serious Findings: 0

Mishaps / Close Calls: 1

-Close Call: 1

1. A can of Rust-Oleum spray paint fell from level ten, to the base of the A-3 Test Stand. There was no damage and no one was injured. No workers admitted to dropping the can and it may have rolled off the stand through an opening.





Construction Safety

Questions?





Construction Safety

Have a SAFE month!