



Construction Safety

SSC Construction Inspection Safety Findings/Stats

April 2017





Contact Info:



NASA Safety

Donna Dubuisson

donna.a.dubuisson@nasa.gov

228-688-2663 phone 288-688-3701 fax

Jesse Lamonte

jesse.m.lamonte@nasa.gov

228-688-1422

228-688-2760 fax

Robert Simmers

robert.e.simmers@nasa.gov

228-688-1877

228-688-3701 fax

http://constructionsafety.ssc.nasa.gov/



Contact Info:



BASTION/SACOM Safety

Donald Smith, CHST donald.g.smith-1@nasa.gov 228-688-1085 phone 228-688-3701 fax

John Lindsay, CSP john.d.lindsay@nasa.gov 228-688-2557 phone 288-688-3503 fax Mark Bridenbeck, TES

mark.a.bridenbeck@nasa.gov

228-688-1732 phone

228-688-3701 fax

Chris Davis, ASP
christopher.m.davis-1@nasa.gov
225-802-6273 phone
288-688-3503 fax

http://constructionsafety.ssc.nasa.gov/



h Safe

Construction Safety Report: 3 April – 7 April 2017

Findings Total: 0

Serious: 0

Other than Serious: 0



Construction Safety Report: 10 April – 14 April 2017



Findings Total: 2

Serious: 0


Other than Serious: 2

- <u>B2 STE Phase 1</u>: Contractor failed to use required ground fault circuit interrupter.
 Ref:29CFR1926.404 (b) (1) (ii). Corrected on the spot. SHEtrak Closed
- <u>Cryogenics Timber Replacement</u>: Contractor employee operating a mini-excavator on Tuesday the 11th, without first completing the required pre-use equipment inspection and its documentation. Ref: SCWI-8715-0008 Section 6.8.3. Corrected on the spot. SHEtrak Closed





Construction Safety Findings:







Construction Safety Findings:

d DAILY	- 0	Equip	ment	MI	NI	EX			Balanta di
	Monday		Tuesday		Wednesday				F
	AM	PM	AM	PM	AM	PM	AM	PM	AM
leaks,									
	1								
	1.								-
rayed,	-			-					
	1								
dded	~								
it							1	,	
)	-							,,	_
	1							-	
	V								
hts,									
	1								
	All 1	2							



Construction Safety Report:



17 April – 21 April 2017

Findings Total: 1

Serious: 0

Other than Serious: 1

— HPG: While performing safety inspections on the Cross Country High Pressure Gas project at the E-Complex, the Construction Manager discovered that the contractor had completed two road crossing trenches, but only had one dig permit and one line drawing attached. The contractor had assumed that one dig permit authorized both road crossings. Immediately the contractor performed a safety stand-down to train construction personnel on the requirements for dig area line drawings and dig area permit approvals. Ref: SSTD-8070-0119-MISC "Dig Permit Standard" Section 5.1.5.f. SHEtrak finding closed and training record attached.





Approved Dig Permit Area







Safety Stand-Down

HEALTHEON	COMPLEX - DIS-PERMIT 1012 Safety Sign-in STAND-DOUGHS Date: 4-20-					
PRINT NAME	COMPANY	Signature				
Roase LaDase	WATURESAL STRUTTERS	12 11				
Zachary Cuevas	Universal Services	Below Co				
Paul Homcock	Universal Services	Drul Honsey				
William Clitron	VINITE SECULAR	Alling Cliff				
Francis A. Spiers	Universal Services Universal Services	A 5				
TAKEN T. NECHKSON	aniversal services	Things In January				
YESON T. NUCHELSON	UNIVERSAL SERVICES	and the state of				
THAD SMITH	UNIDUISAL SCIULOS	Charles S				
Glan Farmer	aniversal services	Sylvasin				
	+					



Construction Safety Report: 24 April – 28 April 2017



Findings Total: 0

Serious: 0

Other than Serious: 0





OSHA's Stop Falls Stand Down

- https://www.osha.gov/StopFallsStandDown/
- •OSHA and SSC Participates in the "Stand Down For Fall Protection"
- •We encourage contractor full support and participation
- •We encourage you to conduct a one time stand-down to discuss and demonstrate Fall Protection and share the importance of it in saving lives.
- Please use a sign-in roster if participating

•May 8-12-2017





Questions?

http://constructionsafety.ssc.nasa.gov/





North Meets South

http://www.bing.com/videos/search?q=bud weiser+how+you+doin+jersey&view=detail &mid=0DFDE355053DBBEB91B40DFDE3 55053DBBEB91B4&FORM=VIRE

Have a Safe month!