



Mission Success Starts With Safety



# Construction Safety

---

SSC Construction Inspection  
Safety Findings/Stats

November 2016



Mission Success Starts With Safety



# Contact Info:

NASA Safety

---

Donna Dubuisson

[donna.a.dubuisson@nasa.gov](mailto:donna.a.dubuisson@nasa.gov)

228-688-2663 phone

288-688-3701 fax

Jesse Lamonte

[jesse.m.lamonte@nasa.gov](mailto:jesse.m.lamonte@nasa.gov)

228-688-1422

228-688-2760 fax

Kathy Cooper

[kathy.a.cooper@nasa.gov](mailto:kathy.a.cooper@nasa.gov)

228-688-1747

228-688-3701 fax

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



# Contact Info:

BASTION/SACOM Safety

---

Donald Smith, CHST

[donald.g.smith-1@nasa.gov](mailto:donald.g.smith-1@nasa.gov)

228-688-1085

228-688-3701 fax

Mark Bridenbeck

[mark.a.bridenbeck@nasa.gov](mailto:mark.a.bridenbeck@nasa.gov)

228-688-1732

228-688-3701 fax

John Lindsay, CSP

[john.d.lindsay@nasa.gov](mailto:john.d.lindsay@nasa.gov)

228-688-2557 phone

288-688-3503 fax


Robert Necaise

[robert.j.necaise@nasa.gov](mailto:robert.j.necaise@nasa.gov)

228-688-2049 phone

288-688-3503 fax

<http://constructionsafety.ssc.nasa.gov/>



# Construction Safety Report: 31 October– 5 November 2016

---


**Findings Total: 0**

Serious: 0

Other than Serious: 0

**Mishaps/Close Calls: 1**

- **B2 WP3**: On November 2, a worker on the B2 Test Stand sustained a small cut (1" long vertically) to their forehead, directly under the bill of their hard hat when they inadvertently ran into a scaffold cross member on level 11. First aid treatment was provided at the work site/band aids were applied to the injury. The worker was encouraged to seek further treatment at the SSC clinic but declined to do so. (NMIS Close call)



# Construction Safety Report: 07– 12 November 2016

## Findings Total: 1


Serious: 0

### Other than Serious: 1

- **B2 Tarmac** – Contractor failed to label pump sprayer container as required. All chemical containers (Including small transfer containers for an employee's own immediate use) shall be labeled or tagged. Ref: SCWI-1800-0005 5.5

## Mishaps/Close Calls: 1

- **B2 Tarmac**- Contractor failed to properly extinguish and dispose of a lit cigarette, creating a small grass fire. Ref: SCWI-



# Construction Safety Findings: 07 – 12 November 2016







# Construction Safety Report: 14 November – 19 November 2016

## Findings Total: 3

### Serious:1

- **B2 WP3** – Contractor utilizing scaffold without having the required inspection or tag prior to use. Reference: SCWI8715-0001 Paragraph 3.16 Item a

### Other than Serious: 2

- **B2 WP3** – Stored unused oxygen cylinder without required protective valve cap  
Ref: 29CFR1910.253 (b) (2) (iv)
- **B2 WP3** – Extension cord plug connection with visible evidence of strain relief  
Ref: 29CFR1910.334 (a) (2) (ii)

### Mishaps/Close Calls: 1

- **B2 WP3**- On Saturday November 19<sup>th</sup> at approximately 11:05 am, the abatement contractor was using a sanding disc on a grinder in the containment on level 16. Metal slag caught the negative air machine and a small area of the plastic containment on fire. A fire extinguisher was used to quickly put out the fires. The fire department was called and declared the area fire safe. No test stand damages or employee injuries. This incident was entered into NMIS and an incident report is being generated.



Mission Success Starts With Safety



# Construction Safety Findings: 14 – 19 November 2016







# Construction Safety Findings: 14 – 19 November 2016





Mission Success Starts With Safety



# Construction Safety Findings: 14 – 19 November 2016








Mission Success Starts With Safety



# Construction Safety Findings: 14– 19 November 2016





# Construction Safety Report: 21 November – 26 November 2016

---

**Findings Total: 0**

**Serious: 0**

**Other than Serious: 0**

**Mishaps/Close Calls: 1**

- **B2 WP3**- A contractor was unloading a full argon cylinder from a pallet on level 8. The cylinder was not in full grasp and therefore accidentally fell to the grating. The employee stepped backwards to remove the cylinder and tripped over a removable toe board (In yellow). He lightly bumped his head and glasses on the grating, as a result, his safety glasses right side shield caused a minor abrasion to his temple. First-aid not required.







Mission Success Starts With Safety



# Construction Safety Findings: 21– 26 November 2016







# Construction Safety Report: 28 November – 30 November 2016

---

**Findings Total:0**

**Serious: 0**

**Other than Serious: 0**

**Mishaps/Close Calls:0**



Mission Success Starts With Safety




# Construction Safety

---

Questions?

<http://constructionsafety.ssc.nasa.gov/>



Mission Success Starts With Safety



# Hunting Season Safety!

---

Have a Safe month!